DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000952

Address: 333 Burma Road **Date Inspected:** 02-Nov-2007

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 1300 **OSM Departure Time:** 2330 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No N/A **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

34-0006 77, 89 & 114 Meter Mock-Up **Bridge No: Component:**

Summary of Items Observed:

This Quality Assurance (QA) Inspector oversaw QA Inspectors David Smith and Roscoe Dixon performing fabrication inspection out on the shop floor today. Mr. Smith observed tack welding of the 77 Meter Mock-Up diaphragm SA274. On the 89 Meter Mock-Up he observed tack welding of various plates on the diaphragm. Mr. Dixon witnessed welding of lifting lugs the 77 Meter Mock-Up diaphragm SA274 and on the 89 Meter Mock-Up he witnessed grinding of various skin plate assemblies and in bay 7 he witnessed cut material being stored.

All observations/verifications by Quality Assurance staff appeared to be in compliance with the project specifications.

Summary of Conversations:

No conversations held today.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Berger,Bruce	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer